

## PART-1

### Performa For The Safety Of School Building

( To be Filled by the Head of School /Institute )

1. Name of School :

SRI GURU HARGOBIND PUBLIC SCHOOL

2. Location :

THAKKARWAL (LUDHIANA)

3. Plot Area :

2 ACRE

4. Plinth Area :

92742.70 SQ FT

5. Number of Storey :

THREE 02

6. Year of Construction of Building :  
the Following details may be given :

Supervision of the Qualified Engineer

A) Name of the Engineer :

Mandeep Kaur

B) Address :

Village Jodhan Ludhiana

C) Set of Structure Drawing  
used in the

Construction if available :

D) Name of the Architect

MANDEEP KAUR JODHAN

8. Whether the Building has been construction for the Purpose of

A) School

Yes/No YES

B) Residential Purpose and converted  
for use as a school

Yes/ No .....

9. Materials used for Roof :

A) R.C.C slabs

Yes / No YES

B) R.S Joists and Battens

Yes / No .....

C) Wooden Joists and Battens

Yes / No .....

10. Materials used for Walls

A) Mud Mortar

Yes/ No .....

B) Cement Mortar

Yes / No YES

C) Plaster ( i ) Lime Mortar

Yes / No .....

( ii ) Cement Mortar

Yes / No .....

11. Flooring :

A) Conglomerate

Yes / No .....

B) Terrazzo

Yes/No YES

C) Brick Paving

Yes / No .....

12. Detailed Drawing indicating dimensions  
of the rooms along with size and location  
of doors and windows

MAP ATTACHED

Principal  
Sri Guru Hargobind  
Signature with stamp of  
The Head of School/ Institute



## PART-II

( To be Filled by S.D.E. of P.W.D B & R Department )

I have visited the above mentioned school on 03/06/2020 and have visually inspected it from all angles of safety and I found it fit for normal use as School building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned .

In case the building is affected by flood or if there is settlement of walls / foundation or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use upto 31/03/2021.

indicate year upto which it can be used )

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਰਿਸਾਰੀ ਉਪ ਮੰਡਲ  
ਸ਼ਹਿਦਾਸ਼ੀ

*[Signature]*

पृष्ठ 71-72 तारीख 12-06-20/20

1, प्रिमीअफ मी गड उड्डे विर पड्डि मड ४ ० कडा  
प्रिमीअफ मी २ मुचता मी ३ उरिमा कडा ० मी।

2. ਕਾਮਰਾਡੀ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਅੰਦਰ ਹੈ।  
~~ਸੋਸ਼ਲਿਸਟ~~ ਸਾ'ਨੂੰ ਯੂਨਾ ਅਤੇ ਅਮਰੀਕੀ ਕਾਮਰਾਡੀ  
 ਰਾਹੀਂ ਉਤਸ਼ਾਹ ਮਾਰ ਰਿਹਾ ਹੈ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਵਿਸਾਰੀ/ਉਪ ਮੰਡਲ ਨੰ:3  
ਲੁਧਿਆਣਾ