## Part - 1

## Performa for The Safety School Building (To be filled by the Head of School/ Institution)

1.	Name of School	SRI GURU HARGOBIND PUBLIC SCH		
2.	Location	THAKKARWAL (LUDHIANA)		
3.	Plot Area	2 ACER		
4.	Plinth Area	92742.70 SRFT		
5.	Number of Storey	THREE (03)		
6.	Year of construction of building	HILLS HE STORY OF THE STORY OF		
7.	Supervision of qualified Engineer,			
<i>/</i> .				
	The following details may be given:			
	a. Name of Engineer		MANDEEP KAUR VILLAGE JODHAN	
	<ul><li>b. Address</li><li>c. Set of structure drawing used in</li></ul>		DANN	
		Construction if available		
	d. Name of Architect	MANDEEP KAUR		
8.	Whether the building has been constructed for the purpose of:			
	a. School	(Yes/No)	YES	
	b. Residertial purpose and corver	ted (Yes / No)		
	for use as a school			
9.	Material used for roof:			
	a. R.C.C. slabs	(Yes/No)	YES	
	b. R.S. Joists and Battens	(Yes/No)	The same of	
	c. Wooden Joists and Battens	(Yes/No)	EA - AT WHILE	
10.	Material used for walls:	The second of the	angu's	
	a. Mud mortar	(Yes/No)		
	b. Cement Mortar		YES	
21064	c. Plaster (i) Lime Mortar	(Yes/No) (Yes/No)	10 2000	
11.	(ii) cement Mortar Flooring:	(165/140)		
11.		(Ver /Ne)		
	<ul><li>a. Conglomerate</li><li>b. Terrazzo</li></ul>	( Yes / No) ( Yes / No)	YES	
	b. Terrazzo c. Brick Paving	(Yes/No)		
12. Detailed drawing indicating dimensions				
of the rooms along with size and location			MAP ATTACHED	
of doors and windows			& Baws	
		Sri Guru Hargobing Public School.		
			Thatkarval Distt Lydhian and The Head of the school institution	
			Code: 1630743	

## (To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on  $\underline{09-04-2094}$  and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or curves of roofs etc. immediately inspection of undersigned be arranged to check the stability and safety of the building.

This building can be safety occupied for normal use up to 31-03-2025 (indicate year up to which it can be used)

Sub Divisional Engineer

Sub Divisional Engineer
Construction Sub Division No.3,
PWD B & Re Br. Ludhiana.

अधार में गुरु मुखा जिंडी में 12-4-24 अधार में गुरु मुखा जिंडी अधिकां सार, में में

(ह) राज्यवर्श हिं सीपीव्य देशांत्री वाउदाही हारी बिह्मार पाठा है मी

She Divisional Engineer
Construction Sub Division No.3,
PWD B & R, Br. Ludhiana.